

FORTH PORTS LIMITED

NtM No 1 of 2017


21 February 2017

NOTICE TO MARINERS FIRTH OF FORTH

Buoy off Location – Firth of Forth

Ref Chart 734

Mariners are advised that the yellow special mark buoy (Fl.Y.5s) marking an outfall in position 56° 09.7'N, 003° 01.5'W (off Buckhaven) has reportedly broken its moorings and drifted ashore in the East Wemyss area. The outfall is currently unmarked and mariners are advised to navigate with caution in this area.



Status of previously published notices:

- No 26 of 2009
- No 14 of 2011
- No 26, 36, 41 and 47 of 2015
- Nos 10, 12, 18, 35, 39, 40 and 41 of 2016

G MAITLAND
Harbour Master Forth Outer